


MID-MOUNT ADAPTER

CFMOTO

CForce 625

Code 03.11300

Version 12112023



Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic sales@ironbaltic.com


DOWNLOAD MULTILINGUAL
USER MANUAL



code.ironbaltic.com/u/Fwlp5i50

SPECIFICATION

Pos.	Description	Code	Amount
1	Plow adapter	03.11301K	1
2	Pin 10x40 mm	14.003	2
3	U-clamp long M8x38	14.009	4
4	Locking pin 2mm	OT.07.01.010	2
5	Bolt M6x25 DIN933	OT.02.02.070	3
6	Washer Ø6/18 DIN9021	OT.04.02.020	3
7	Washer Ø8/20 SFS3738	OT.04.03.030	8
8	Nyloc nut M8 DIN985	OT.03.02.040	8




FITTING INSTRUCTIONS

Without Iron Baltic skid plate

Step 1

Remove original skid plate middle part or drill holes for U-clamps and install plow adapter 03.11301K.




FITTING INSTRUCTIONS

With Iron Baltic skid plate


Step 1

Remove skid plate side parts and bolts and washers shown in picture.




Step 2

Install plow adapter 03.11301K.



Step 3

Reinstall skid plate side parts and fasten the oil hole plate with the bolts supplied with the adapter.



IRON BALTIC

IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticLtd

