

# IRON BALTIC

## MID-MOUNT ADAPTER

# KUBOTA

# RTV-X900

Code 03.10200

Version 11112023



**Keep this manual for future reference!**

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic [sales@ironbaltic.com](mailto:sales@ironbaltic.com)


DOWNLOAD MULTILINGUAL  
USER MANUAL



[code.ironbaltic.com/u/9NFnM1Ju](https://code.ironbaltic.com/u/9NFnM1Ju)


# SPECIFICATION

Pos.	Description	Code	Amount
1	Plow adapter	03.10201K	1
2	Installation plate	03.10202K	1
3	Distance bush	05.5405	3
4	Pin 10x40 mm	14.003	2
5	Locking pin 2mm	OT.07.01.010	2
6	Bolt M8x20 DIN933	OT.02.02.180	2
7	Bolt M8x30 DIN933	OT.02.02.200	3
8	Washer 8/20 SFS3738	OT.04.03.030	5




# FITTING INSTRUCTIONS

**Step 1** Remove skid plate original bolts (3 pcs).




**Step 2** Install installation plate 03.10202K.



### Step 3

Install plow adapter 03.10201K. NB! Install bushes 05.5405 between rear holes of the adapter and skid plate.







# IRON BALTIC

IRON BALTIC OÜ  
Joa tee 17  
Vääna 76903  
Estonia / Europe

+372 6 533 711  
[sales@ironbaltic.com](mailto:sales@ironbaltic.com)

[www.ironbaltic.com](http://www.ironbaltic.com)  
[www.facebook.com/ironbaltic](https://www.facebook.com/ironbaltic)  
[www.youtube.com/user/ironbalticLtd](https://www.youtube.com/user/ironbalticLtd)

