

IRON BALTIC

MID-MOUNT ADAPTER

ZFORCE

1000 Sport

Code 03.11700

Version 12112023



Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic sales@ironbaltic.com


DOWNLOAD MULTILINGUAL
USER MANUAL



code.ironbaltic.com/u/URbGqosY

SPECIFICATION


Pos.	Description	Code	Amount
1	Plow adapter	03.11701K	1
2	Installation plate	03.5102	2
3	Distance bush	05.7102	2
4	Pin 10x40 mm	14.003	2
5	Locking pin 2mm	OT.07.01.010	2
6	Pipe clamp bracket 48mm	OT.05.04.060	2
7	Bolt M8x12 DIN933	OT.02.02.168	2
8	Bolt M8x35 DIN933	OT.02.02.210	2
9	Bolt M8x45 DIN933	OT.02.02.230	2
10	Carriage bolt M8x80	OT.02.05.084	4
11	Washer Ø8/20 SFS3738	OT.04.03.030	6
12	Washer (large) Ø8/24 DIN9021	OT.04.02.040	2
13	Nut M8 Nyloc DIN985	OT.03.02.040	4



FITTING INSTRUCTIONS



Step 1

Install installation brackets 03.5102.



Step 2

Install plow adapter. If installing adapter WITH IronBaltic skid plate, use bolts M8x45(Pos.9), if installing adapter WITHOUT IronBaltic skid plate, use bolts M8x35(Pos.8). NB! When installing with IronBaltic skid plate, remove middle and front part connecting plates.



IRON BALTIC

IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticLtd

