

# IRON BALTIC

## FRONT MOUNT ADAPTER

# AODES

## Workcross 650 / 1000

Code 03.15600

Version 25062024



**Keep this manual for future reference!**

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic [sales@ironbaltic.com](mailto:sales@ironbaltic.com)

Iron Baltic Ltd | +372 653 3711 | [sales@ironbaltic.com](mailto:sales@ironbaltic.com) | [www.ironbaltic.com](http://www.ironbaltic.com)


DOWNLOAD MULTILINGUAL  
USER MANUAL



[code.ironbaltic.com/u/0VWjb9HW](http://code.ironbaltic.com/u/0VWjb9HW)


# SPECIFICATION

Pos.	Description	Code	Amount
1	Adapter	03.15601K	1
2	Bush 28 mm	03.10605	2
3	Bolt M8x25 DIN933	OT.02.02.190	2
4	Bolt M10x25 DIN933	OT.02.02.317	2
5	Bolt M10x55 DIN933	OT.02.02.342	2
6	Washer Ø8/20 SFS3738	OT.04.03.030	2
7	Washer M10 DIN125	OT.04.01.040	6
8	Nyloc nut M10 DIN985	OT.03.02.050	2




# FITTING INSTRUCTIONS

**Step 1** Remove original bolts and winch roller.




**Step 2** Install adapter (Pos.1) with winch roller. For fastening use M8x25 bolts (Pos.3), M10x25 bolts (Pos.4), Ø8/20 washer (Pos.6), M10 washers (Pos.7).





### Step 3

Install bushes (Pos.2) on the adapter (Pos.1). For fastening use M10x55 bolts (Pos.5), M10 washers (Pos.7) and M10 nyloc nuts (Pos.8).









# IRON BALTIC

IRON BALTIC OÜ  
Joa tee 17  
Vääna 76903  
Estonia / Europe

+372 6 533 711  
[sales@ironbaltic.com](mailto:sales@ironbaltic.com)

[www.ironbaltic.com](http://www.ironbaltic.com)  
[www.facebook.com/ironbaltic](https://www.facebook.com/ironbaltic)  
[www.youtube.com/user/ironbalticLtd](https://www.youtube.com/user/ironbalticLtd)

