

IRON BALTIC

SNOW PLOW MOUNTING KIT

POLARIS 570 Ranger

Code 03.5100

Version 06112023



Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic
sales@ironbaltic.com


DOWNLOAD MULTILINGUAL
USER MANUAL



code.ironbaltic.com/u/0EGVZ1tS

SPECIFICATION

Pos.	Description	Code	Amount												
1	Adapter	03.5101K	1												
2	Installation plate	03.5102	4												
3	Pin 10x40 mm	14.003	2 <tr><td>4</td><td>Cotter pin 2 mm DIN 11024</td><td>OT.07.01.010</td><td>2</td></tr> <tr><td>5</td><td>Bolt M8x110 DIN931</td><td>OT.02.01.020</td><td>8</td></tr> <tr><td>6</td><td>Washer M8 SFS3738</td><td>OT.04.03.030</td><td>8</td></tr>	4	Cotter pin 2 mm DIN 11024	OT.07.01.010	2	5	Bolt M8x110 DIN931	OT.02.01.020	8	6	Washer M8 SFS3738	OT.04.03.030	8
4	Cotter pin 2 mm DIN 11024	OT.07.01.010	2												
5	Bolt M8x110 DIN931	OT.02.01.020	8												
6	Washer M8 SFS3738	OT.04.03.030	8												



FITTING INSTRUCTIONS

Step 1 If ATV is fitted with IronBaltic skidplate then remove sideprotections.



Step 2 Place and hold the installation plate 03.5102 behind the ATV frame. Use bolts M8x110 and install the snow plow adapter plate. Re-install side protections and tighten the adapter bolts.



IRON BALTIC

IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticLtd

