

IRON BALTIC


MID-MOUNT ADAPTER

CFORCE

850 / 1000

Code 03.8500

Version 10112023



Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic sales@ironbaltic.com


DOWNLOAD MULTILINGUAL
USER MANUAL



code.ironbaltic.com/u/eGQtVich

SPECIFICATION



Pos.	Description	Code	Amount
1	Plow adapter	03.8501K	1
2	Plate	03.8407	2
3	Pin 10x40 mm DIN 1444	14.003	2
4	Locking pin 2mm DIN 11024	OT.07.01.010	2
5	Bolt M8x40 DIN933	OT.02.02.220	4
6	Bolt M8x80 DIN933	OT.02.02.270	4
7	Washer 8/20 SFS 3738	OT.04.03.030	12
8	Nylock nut M8 DIN 985	OT.03.02.040	4



FITTING INSTRUCTIONS




Step 1

Remove original middle plastic and bolts indicated with arrows. If using IronBaltic plastic skid plate, remove also skid plate connecting bolts indicated with arrows.



Step 2

Install plow adapter.



IRON BALTIC

IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticLtd

