



SPEED LIMITER REMOVED ECU

CFMOTO CFORCE 400/450 (2023+)
Models with BOSCH MSE8.0 ECU's

Code 96.2900

Version 12092024



Distributor **IronBaltic, Estonia**

Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic
sales@ironbaltic.com

SPECIFICATION

Pos.	Description	Code	Amount
1	ECU for CFORCE 400/450 (2023+)	96.2900ML	1
2	Sticker (IronBaltic)	PM.13.05.007	1



**ONLY FOR OFF-ROAD
AND/OR RACING USE!**



The end user is responsible for using this ECU with removed speed limiter and taking care of any penalties set by local authorities. This is an electronic device, and no warranty or replacement is implied. All sales are final.

INSTRUCTIONS

1. Make sure the vehicle ignition is turned OFF!
2. Disconnect battery negative terminal.
3. Locate the ECU and remove necessary screws to access the ECU.
4. Carefully disconnect the old ECU. Be careful not to damage contacts between ECU and connector.
5. Carefully connect new ECU. Be careful not to damage contacts between ECU and connector.
6. Reconnect the battery negative terminal.
7. Switch on the ignition and wait 60 seconds for the new ECU to communicate with the vehicle.
8. Start the engine and let it idle for 5 minutes to adapt to new values.
9. In some rare cases, fault code or engine light can occur. Usually, it is cleared after couple of engine starts and stops OR the fault code can be cleared with OBD diagnostic cable.
10. Have fun with your new ECU!



IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticLtd